ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	5	Jakkuru
Street ID	**Street Name**	**Significant Landmark**
W0243, W0249, W0247, W0245, W0257, W0237, W0235, W	Chowdeshwari Temple Behind Rd, NA, 4th Crs, Maheshwaramma Temple Behind Rd	(shivapura)of kogilu village
Segment No.	**Total Length (m)**	
5/C-W0243/S121141	1134.75	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	145.53	77.623787	13.118408	77.624002	13.119706	W0257	RI-A18
2	113.23	77.623058	13.118786	77.623238	13.119794	DEAD END	RI-A18
3	113.82	77.622787	13.118813	77.622916	13.119835	DEAD END	DEAD END
4	194.52	77.622638	13.119885	77.622367	13.118147	DEAD END	DEAD END
5	194.50	77.622360	13.119929	77.622089	13.118191	DEAD END	DEAD END
6	66.15	77.622006	13.119466	77.621947	13.118871	W0233	DEAD END
7	307.00	77.621402	13.119554	77.624211	13.119212	W0233	DEAD END

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to Roads and Drains at Surrounding areas (shivapura)of kogilu village in ward no 05 Byatarayanapura Sub-Division Yelahanka zone	4900000	2015
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Improvements to Roads and Drains at Surrounding areas (shivapura)of kogilu village in ward no 05 Byatarayanapura Sub-Division Yelahanka zone	005-16-000015
Work Order No.	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/206/2015-16	12/02/2016	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
12/02/2016	11/02/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
VASANTH		0.00
Phone No.	**E-Mail ID**	
9449109576		

Field Inspection Details

Number of Trees	Any Other Information	Name
10		Chandrakanth
Date of Inspection	**Remarks**	
09/06/2016	completed	

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 5 **Ward Name:** Jakkuru **Street ID:** W0243, W0249, W0247, W0245,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	09/06/2016	09/07/2016	COMPLETED
SE	VASU K M	09/06/2016	09/07/2016	COMPLETED
EE	YARAPPA REDDY	09/06/2016	09/07/2016	COMPLETED
AEE	J N LOKESH	09/06/2016	09/07/2016	COMPLETED
AE	CHANDRAKANTH	09/06/2016	09/07/2016	COMPLETED
AE	CHANDRAKANTH	09/06/2016	09/07/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 5 **Ward Name:** Jakkuru **Street ID:** W0243, W0249, W0247, W0245,